Stable supervisory control of flexible manufacturing systems with fixed supply and demand rates

PETER C. Y. CHEN* and W. M. WONHAM†

In this article, we develop a method for computing a stable supervisory control for a class of manufacturing systems (consisting of reconfigurable processors and buffers with limited capacities) with fixed supply and demand rates. It is shown that, with this method, we are able to (i) decide constructively whether a stable supervisory control exists for a given manufacturing system, and (ii) compute the stable supervisory control if it exists. Furthermore, the stable supervisory control thus obtained is complete in the sense that it contains all "safe" sequences (of possibly concurrent buffer and processor activities) which guarantee the stability of the system. An example is presented to illustrate the proposed method. Implications and computational complexity associated with this method are discussed.

1. Introduction

We consider the problem of controlling flexible manufacturing systems consisting of reconfigurable processors and buffers with limited capacities. We describe a manufacturing system as flexible if its processors can be reconfigured to perform different types of tasks. A processor is reconfigurable if its characteristics (physical or otherwise) can be altered in order to perform a given task. For example, a Computer-Numerical-Control (CNC) machine with a set of fixtures can be considered as a reconfigurable system, since performing a new task would involve changing fixtures and activation of a particular CNC program. Reconfiguration of a processor usually requires a certain amount of time.

The dynamics of such manufacturing systems is characterized by the requirement that the rate at which new parts enter the system (i.e., the supply rate) and the rate at which finished parts leave the system (i.e., the demand rate) are fixed. The stability of such a system is characterized by the requirement that the capacities of the buffers must not be exceeded during operation. Since a processor must receive parts from and deliver parts to the buffers, the supply and demand rates thus impose a timing constraint on the operation of the processor. It is in this context that we define a manufacturing system as *stable* if the capacity of the individual buffers within the system is not exceeded during operation.

Management of such systems becomes complicated when a processor is required to perform different tasks on different types of parts. For instance, suppose a processor is required to perform different tasks on two types of parts, each having its own input and output buffers and its own supply and demand rates. To maintain the prescribed supply and demand rates while ensuring that the buffers do not overflow, the processor must be reconfigured so that a certain mix of the two types of parts is processed. The mechanism which manages the activities of the processor is referred to as a supervisory control. By making timely decisions on when to start

*Bachelor of Technology Programme, Faculty of Engineering, National University of Singapore, EA-07-32, 9 Engineering Drive 1, Singapore 117576. Email: engchenp@nus.edu.sg

†Department of Electrical and Computer Engineering, University of Toronto, 10 King's College Road, Toronto, Ontario, Canada M5S 3G4. Email: wonham@control.toronto.edu

processing a part and when to reconfigure a processor, a stable supervisory control guarantees that the buffers do not overflow during operation.

The fixed supply and demand rates of a manufacturing system have a significant interpretation under the concept of "hard-real-time manufacturing". Hard-real-time manufacturing differs from conventional approaches to management of manufacturing operations in that time is a critical aspect of operation. To support hard-real-time operation, a manufacturing system must *guarantee* the completion of a given task by a specific deadline. Failure to meet such deadlines is not acceptable. The benefits of adopting the hard-real-time approach to manufacturing include: (i) that manufacturing resources can be more efficiently allocated because the exact time and duration of utilization of a device are known, (ii) that planning of enterprise-wide activities can be carried out more effectively because manufacturing tasks are guaranteed to be completed by specific deadlines, and (iii) that production flow becomes more manageable because problems associated with tardiness of task execution can be avoided.

A manufacturing system operating at a supply rate of one part per t_1 minutes and a demand rate of one part per t_2 minutes is one example of hard-real-time manufacturing. The system must take in one new part every t_1 minutes, and must deliver a finished part every t_2 minutes. The key point is that the intake or the delivery of a part must occur between closely spaced time instants; neither earlier nor later is acceptable.

In this article, we develop a method for computing a stable supervisory control for manufacturing systems with fixed supply and demand rates. Our method is based on the theory of supervisory control of discrete-event systems (DES). A DES is a dynamical process which evolves through abrupt occurrence of events. In a logical DES, the system is characterized by a set of states and transitions (also called events) among these states. The behavior of the system is thus described by a sequence of events. The occurrence of an event (caused by some unmodelled mechanism internal or external to the system) instantaneously moves the system to a new state.

In a timed discrete-event system (TDES), the behavior of the system is also influenced by the temporal characteristics of the event sequence. Specifically, in a TDES, the occurrence of an event could be triggered either by some unmodelled mechanism acting on (or in) the system, or by the passage of time. Supervisory control of a TDES in essence means timely disablement of certain events in the transition structure of the TDES such that its behavior meets certain specifications. A supervisor which prevents events from occurring only when absolutely necessary is described as minimally restrictive. The minimally restrictive behavior of a supervisor is represented by the so-called supremal controllable sublanguage.

To investigate the problem of controlling a manufacturing system for hard-real-time operation, we first model the operation of the buffers and the processor as TDES. We then compute the supremal controllable sublanguage for the TDES with respect to the desired timing behavior of the manufacturing system. To determine whether a system can be controlled such that the supply and demand rates are satisfied while ensuring that the buffers do not overflow, we simply check whether the supremal controllable sublanguage corresponding to this TDES is non-empty. If it is non-empty, then it represents all "safe" sequences of buffer and processor operations (possibly concurrent) which guarantee that the manufacturing system will remain stable while maintaining the desired supply and demand rates. In the context of this article, a safe sequence is a sequence that never takes the system to a state from which, after the further execution of events whose possible occurrence cannot be suppressed, the system would deviate from the desired behavior.

The contribution of this work lies in the development of a formal constructive method for hard-real-time control of dynamical manufacturing systems. With this method, we are able to (i) decide constructively whether a stable supervisory control exists for a given manufacturing system, and (ii) compute the stable supervisory control if it exists. Furthermore, the stable supervisory control thus computed is complete, in the sense that it contains all safe sequences of part processing and processor reconfiguration that produce the desired dynamical behavior of the manufacturing system.

The remainder of this article is organized as follows. Section 2 briefly surveys the relevant literature, and formulates the problem under consideration. Section 3 introduces the theory of supervisory control of TDES. Section 4 describes the proposed method for modelling flexible manufacturing systems with fixed supply and demand rates in the TDES framework, and for synthesizing stable supervisory control for such systems. Section 5 presents an example to illustrate the proposed method. Section 6 discusses some implications of this work and the computational complexity associated with the proposed method.

2. Background and problem formulation

Control of manufacturing systems has been extensively investigated over the last few decades, with its origin found mainly in *job-shop scheduling* (e.g., Jackson 1955, Lawler 1983). Such investigations mostly focus on developing methods for managing the activities of various resources to achieve “optimal” operation of the manufacturing system, under the premise that certain tolerance (such as missing a deadline by a certain amount of time) is permitted.

The criteria of optimality range from minimum processing time and maximum utilization of resources, to least penalty paid for completing a task before the deadline or for missing the deadline (e.g., Asano and Ohta 1996, Cheng and Janiak 1994, Choi and Hitomi 1994, Karacapilidis and Pappis 1993, Lipske 1996, Luh and Hoitomt 1993, Perkins and Kuma 1989, Weng and Ventura 1996). For instance, Weng and Ventura (1996) investigate the problem of single-machine earliness-tardiness scheduling for a given common due date with tolerances. The objective was to minimize the mean absolute deviation of job completion times with the due date tolerance varying from job to job. In Perkins and Kumar (1989), a class of scheduling policies is presented for manufacturing systems where the processing sequences of parts are fixed and parts are to be produced at specific rates (though deviation within certain tolerance is allowed), with consideration for reconfiguration time.

As manufacturing systems become more complex, various formal techniques have been introduced to model, analyze, and control the behavior of such systems. Such formal techniques include max-plus algebra and petri nets. Application of max-plus algebra to manufacturing systems addresses the problem of synchronization of the activities of the various components in the system (Cohen *et al.* 1985). By modelling the timing behavior of a system as a set of “linear” equations in the framework of max-plus algebra, a complete characterization of the asymptotic behavior of the system can be computed. Petri nets have been widely used for modeling manufac-